

CASE STUDY:

Wheeler Army AF Base Tile Walls & Floors – O’Ahu Hawaii



Situation: Tile in the various base restrooms had become stained and the grout retained imbedded grime that had become impossible to remove by routine cleaning.

Solution: Surfaces received a complete deep cleaning and were then treated using the MicroGuard tile treatment system. Work was accomplished by long-time Adsil customer, Grace Pacific, Inc.

Results: The tile & grout were beautifully restored. Cleaning maintenance was dramatically improved and a new customer was thoroughly satisfied.