

## CASE STUDY:

### Fast food Restaurant at 5451 Roosevelt Blvd, Jacksonville, FL



**Solution:** The Adsil MicroGuard®/MicroGrip™ Anti-Skid Floor System was applied to ceramic tile in customer service areas and on walkways in dining room areas to reduce slip & fall liability risk. MicroGuard® AD703 Clear was applied, without the MicroGrip™ Anti-Skid Additive, under tables, in bathrooms and in seating areas.

### Results:

- Service areas and walkways are safer, even when wet.
- Design appearance was not hindered, tile color remains intact.
- Employees are complimentary of the enhanced safety of the work areas.
- Liability risk, due to unsafe floor conditions, has been diminished.
- MicroGrip™ Anti-Skid Floor System is easy to clean and maintain.
- Floor resists staining from soft drink and ketchup spills.
- Grout remains sealed, clean and bright.
- Floor does not need to be waxed or buffed.